

STEP 1 SHUTDOWN SEQUENCE

- Turn Off 1 (Inverter AC Switch)
- Then Turn Off 2 (Inverter DC Switch)
- Turn Off **3** (Battery DC Switch)
- Wait 5 Minutes
 (All lights on the Inverter are off)

STEP 2

RESTART SEQUENCE

- Turn On 3 (Battery DC Switch) First
- Then Turn On 1 (Inverter AC Switch)
- Finally Turn On 2 (Inverter DC Switch)
- Wait 5 Minutes